

Notes

- 1. Leak Tested To 5x10E-10 standard cc/se of He.
- Dimensions Symmetrical About Centerlines.
 This is a vacuum safety 'over pressurization prevention' device. As such, ruptured discs can not be repaired, and must be replaced with a completely new unit.
- 4. Be Careful Of Burst Disc Foil, It Is Very Fragile



Rev.	Description	Date	Made By	Approval
Α	Initial Release	3/25/2009	CR	СМ
В	Changed Burst Disc And Adapter To New Version	7/1/2020	Farrell	





Section A-A

Accu-Glass Products Inc. 25047 Anza Drive Valencia, CA 91355 T 818-365-4215 F 818-365-7074 www.accuglassproducts.com

UNCONTROLLED WEB DRAWING

Proprietary and Confidential The information contained in this drawing is the sole property of Accu-Glass, Products Inc. Any reproduction, in part or as whole, without the written permission of Accu-Glass Products, Inc., is strictly prohibited.

	Material					
	Stainless Steel					
	Tolerances, unless otherwise specified					
	.X \pm . 030					
	.XX \pm .010	Angles ± 0.5°				
	.XXX ± .005	Finish 63Ra				

Title			PBD-K16		
Drawn by Date	CR 3/25/2009	No.	112072		Rev.
Approved	СМ			She	et 1 OF 1